Multiple Fobbing Products If the cellar any warmer / colder than need to have your CTC fixed. normal? Check the gas at the coupler. gas, check another product using the same gas (check the colour of the Point the couple away from you, towards the floor and depress the handle for a couple gas line) of seconds If it is blue then check a 2nd Flo-Jet, if no ticking, check the Air Compressor If not, follow the oottom left pipe or If fitted, are the the pump) to the SRV then turn the ticking, what color gas pumps ticking? is the gas line? If grey, white or green, check a coupler with switch/lever to the opposite direction the same gas pipe by the keg, if there is no gas, change that gas bottle If the label shows If only Smooth 60/40 then change the gas bottle. You will also have to change the Kegs as the CO2 will have dissolved into the liquid Stouts affect, check the label or the gas bottle. If it was longer than 7 days please do a line clean and call Innserve directly if there are further issues